

PRECISION
AIRMOTIVE LLC
Service Information
Letter - Fuel Systems

SIL MS-13 Revision 1

SMALL RECIPROCATING ENGINES

All Carburetors

Issued 08/09/06

Page 1 of 1

**SUBJECT: New Accelerator Pump Discharge Check Valve Assembly & the
Removal of Throttle Shaft O-Rings and Retainers**

Revision 1 provides list of affected major repair kits in relationship to HA-6 carburetors

PURPOSE: To provide information.

- A) **EFFECTIVITY:** This Service Information Letter is applicable to model HA-6 carburetors and major repair kits, part numbers:

Carburetor	Major Repair Kit	Carburetor	Major Repair Kit	Carburetor	Major Repair Kit
10-5092	286-1613	10-5224	286-1761	10-5282	286-2014
10-5189	286-1718	10-5230	286-1762	10-5283	286-2015
10-5206	286-1731	10-5235	286-1763	10-6019	286-2020
10-5206-1	286-1733	10-5253	286-1768	10-6019-1	286-2020
10-5210	286-1732	10-5255	286-1767	10-6030-1	286-2060
10-5219	286-1760				

- B) **COMPLIANCE:** Information Only.

- C) **DESCRIPTION:** The following 2 changes have occurred:

- 1) New accelerator pump discharge check valve assembly part number 36-625 replaces the existing part number 36-596.
- 2) Removal of 2 each of part number 55-255 throttle shaft o-ring retainers and 2 each of part number 44-220 throttle shaft o-rings.

PUBLICATIONS AFFECTED: The applicable illustrated parts list pages in carburetor manual # MSAFSM Rev C have been revised to reflect the listed changes.