

Volare Carburetors, LLC

125 Piedmont Avenue
Gibsonville, N.C. 27249, USA
Phone: 336-446-0002 // 0005
Fax: 336-446-0007
Email: customerservice@volarecarbs.com
Website: www.volarecarbs.com

Service Bulletin: SB-7 Rev A

Original Date: May 12th, 2010

Revision Date: May 27th, 2010

SUBJECT – MIXTURE CONTROL STOP REPAIR – HA-6™ TYPE CARBURETORS.

1. **Applicability:** HA-6™ model float carburetors manufactured by Volare Carburetors LLC (“Volare”), and its predecessors Precision Airmotive Corporation, Facet Aerospace Products Company, and Marvel-Schebler™ (Borg-Warner) (hereinafter “Volare”).
2. **Reason:** 1. To inform the industry that a FACTORY repair for HA-6™ mixture control stops is now available.
2. To inform service technicians that these parts are **APPROVED** for use in HA-6™ carburetors, see figures 1 & 2.
3. **Instructions:** If HA-6™ mixture control stops are found to be excessively worn, and if you wish to have this repair accomplished, contact Volare @ (336) 446-0002 ext. 005, or email customerservice@volarecarbs.com.




FIGURE 1
ORIGINAL CONFIGURATION
CAST INTEGRAL STOPS




FIGURE 2
DISCRETE MIXTURE STOP PARTS
EXPLODED VIEW

Distributed by:

TEMPEST
excellence

SB-7, Revision A, Issued 05/27/2010

Original Issue Date: 05/12/2010