



Service Information Letter - Fuel Systems

SIL MS-8

SMALL RECIPROCATING ENGINES

MA-4SPA

Issued 01/02/03

Page 1 of 1

SUBJECT: New Pump Plunger Assembly for Model MA-4SPA Carburetors

PURPOSE: To provide instructions for installing 194-800 Pump Plunger Assembly in place of 194-581.

- A) **EFFECTIVITY:** This Service Information Letter is applicable to all model MA-4SPA carburetors.
- B) **COMPLIANCE:** Information Only.
- C) **DESCRIPTION:** A new accelerator pump plunger assembly, part number 194-800, has been incorporated into production at Precision Airmotive Corporation. The existing 194-581 plunger assemblies may be used until stock is exhausted.
- D) **PUBLICATIONS AFFECTED:** The following illustrated parts list pages in carburetor manual #FSM should be marked to reflect the change from 194-581 to 194-800:

A10-3678-12
10-3678-32
A10-4910
A10-4910-1
A10-5009
A10-5062
A10-5135
A10-5217