



14800 40th Avenue NE
MARYSVILLE, WASHINGTON 98271
FAA-PMA FACILITY #PQ111NM

Service Bulletin Fuel Systems

Bulletin No.: MSA-12

Date: 8/1/06

SUBJECT: COMPLETE REVISION OF CARBURETOR MAINTENANCE MANUAL

- 1) **DESCRIPTION:** Precision Airmotive LLC has released a new revision to the float carburetor maintenance manual, Form # MSAFSM, Revision C. This manual is a complete revision, and the previous version, Form # MSAFSM, Revision B is now obsolete, as are all other prior versions.
- 2) **CHANGES:** This manual incorporates **numerous** changes to the text of the overhaul section and must be reviewed **carefully** by maintenance personnel to ensure that all appropriate procedures are followed during carburetor maintenance work. For example, one significant change is a new requirement that all carburetors be subject to non-destructive testing (NDT) inspection methods during the overhaul process.
- 3) **COMPLIANCE:** Within 60 days of this bulletin, all maintenance work on Precision Airmotive float carburetors (including those previously manufactured by Marvel Schebler, Borg-Warner, and Facet) must be performed pursuant to the new carburetor maintenance manual (Form #MSAFSM, Revision C, dated June 23, 2006). After 60 days, maintenance work that does not conform to the procedures in the new manual will not be considered by Precision Airmotive to be in conformance with the manufacturers' instructions.
- 4) **AVAILABILITY:** The current version of the manual (Form #MSAFSM Revision C) is available only from Precision Airmotive.
- 5) **UPDATES:** This maintenance manual is sold with a one calendar year update service. This service must be renewed each year to ensure receipt of continued updates.