

PRECISION
AIRMOTIVE LLC
Service Information
Letter - Fuel Systems

SIL MS-17

SMALL RECIPROCATING ENGINES

All Carburetors

Issued 2/8/07

Page 1 of 1

SUBJECT: New Pump Discharge Check Valve & Spring

PURPOSE: To provide information.

- A) **EFFECTIVITY:** This Service Information Letter is applicable to model MA-4-5 carburetors and major repair kits, part numbers:

Carburetor	Major Repair Kit
10-3878	286-1670
10-5193	286-1719
10-5288	286-2017
10-6054	286-1670
10-6102	286-2101

- B) **COMPLIANCE:** Information Only.

- C) **DESCRIPTION:** The following 2 changes have occurred:

- 1) New Pump Discharge Check Valve part number 34-91 replaces the existing part number 34-72 (MSAFSM; IPL Figure 2, Item 38).
- 2) Addition of 1 each of part number 24-A115 spring (MSAFSM; IPL Figure 2, Item 34A).

PUBLICATIONS AFFECTED: The applicable illustrated parts list pages in carburetor manual # MSAFSM Rev C will be revised to reflect the listed changes.