

**Marvel-Schebler Aircraft
Carburetors LLC**

2208 Air Park Drive
Burlington, N.C. 27215, USA
Phone: 336-446-0002
Email: customerservice@msacarbs.com
Website: www.msacarbs.com

Service Bulletin: SB-25 Rev O

***Issue Date: April 20, 2021**

**SUBJECT: THROTTLE SHAFT for MA-5®
CARBURETORS**

1. **Applicability:** This service bulletin applies to MA-5®, P/N 10-5043 carburetors made by Marvel-Schebler Aircraft Carburetors, LLC and to carburetors of the same models manufactured by Marvel Schebler Company, Borg-Warner, Facet, Precision Airmotive, and Volare' (collectively referred to herein as "MSA Carburetors").
2. **Reason:** To inform the industry that, as of March 2018, production of throttle shaft part number 13-1525 was discontinued. Throttle shaft part number 13-1525 is replaced by part number 13-1522. Part number 13-1525 may be used until supplies exhausted.
3. **Compliance:** Use appropriate service information when servicing MSA Carburetors.