

MARVEL-SCHEBLER PRODUCTS DIVISION
BORG-WARNER CORPORATION

MAIN OFFICE AND FACTORY
DECATUR, ILLINOIS, U. S. A.

September 2, 1965

SERVICE BULLETIN

#A2-65

TO: All Manual Holders


SUBJECT: Carburetor Replacement on the Lycoming O-540-A1A Engines.

Please mark your records to indicate; carburetors, part #A10-4057 and A10-4057-1, are obsolete and that you can use part #10-4404 as the factory authorized replacement.

IMPORTANT

Do not replace the A10-4404 with A10-4057 or A10-4057-1. This is not authorized by the engine manufacturer.

MARVEL-SCHEBLER PRODUCTS DIVISION


R. T. Massey
Service Sales Manager

mb

