Marvel-Schebler/Tillotson

Division Borg-Warner Corporation, 2195 South Elwin Road, Decatur, Illinois 62525



SERVICE BULLETIN



July 1982

#A1-82

TO: All Registered Manual Holders

SUBJECT: Drain Plugs. Model HA Carburetors


TIME OF COMPLIANCE: Next Overhual or Owners Option.


Some difficulties were experienced in removing the recessed allen type drain plugs, Part #99-34. The design has been changed to use a face seal type Part #99-45 with Gasket #16B-322.

THESE ARE NOT INTERCHANGEABLE.


-Note the difference in thread-

OLD STYLE





NEW STYLE



Pipe Plug style drain plugs and face seal style are not interchangeable. It is easier to remove and install the #99-8 Hex Head type when you service the old style.





·

1

;